THIS YEAR IN MOTOR

An index of the nearly 500 sales, management and service articles that have appeared in this magazine in 1968

SERVICE PROCEDURES

ACCESSORIES

	Month	Page
Servicing Plastic Wheels on Blowers (S)	Feb.	88
Mysterious Coolant Loss (S)	Mar.	58
Radiator Removal (S)	Mar.	58
Speedometer Removal (F)	Mar.	64
Faster Heater Core Removal (F)	Mar.	68
Quick Guide to Flasher Controls	Apr.	28
When Air Conditioners Lose Their Cool	Apr.	32
Heater Core Removal (S)	Apr.	50
Air-Conditioner Installation (S)	May	48
Instrument Cluster Removal (S)	May	52
Instrument Cluster Removal (S)	June	66
Heater Core Removal (S)	June	66
Windshield Wiper Check (S)	June	72
Moisture Removal from Cooler (S)	July	60
Thermostat Installation (F)	July	64
Heater or Cooler Control-Head Removal (S)	Aug.	46
Accessory Fuse Check (S)	Aug.	46
Evaporator Core Removal (S)	Aug.	46
Cluster Removal Caution (S)	Aug.	48
Vent-Hose Repair (F)	Sept.	67
Five Truck Wiper Faults You Can Repair	Oct.	30
Heater Motor Removal (F)	Oct.	38
Wiper-Blade Removal (S)	Oct.	64
Windshield-Wiper Replacement (S)	Oct.	64
Buick Power Top Repair (F)	Nov.	44
Drains Cooler Evaporation (F)	Nov.	96
Adds Oil to Cooler Compressor (F)	Dec.	42

AXLES

	Month	Page
New Specs for Axle End Play (S)	Feb.	86
Differential Repair (F)	July	62
Axle Bearing Replacement (F)	July	64
Tool to Remove Truck Axle Nut (F)	Aug.	68
New Thrust Spacers for Differential (S)	Oct.	60
Bent-Wheel Stud Removal (S)	Oct.	60

BRAKES

	Month	Page
Don't Be Stopped by the New Disc Brakes	Jan.	28
Master-Cylinder Disassembly (S)	Jan.	47
Brake Shudder Check (S)	Jan.	48
Bleeding Power Brakes (S)	Jan.	50
Bleeding Rear Disc Brakes (S)	Feb.	86
Easy Brake-Drum Removal (F)	Mar.	64
Overheating Rear Wheel Brakes (S)	Apr.	48
Bleeding Procedure Revised (S)	Apr.	50
Brake Job Speed-up (F)	Apr.	54
Power-Brake Bottoming (S)	May	56
Emergency Brake Adjustment (F)	May	64
Track Down Disc Brake Trouble Fast	June	32
Check Parking-Brake Adjustment	Aug.	52
Disc-Pad Installation (F)	Aug.	70
Correct Caliper Installation (S)	Sept.	65
Frees Stuck Emergency Cables (F)	Nov.	44
Corvair Brake Cable Installation (F)	Nov.	45
Brake Equalizer-Valve Adjustment (F)	Dec.	43

COOLING SYSTEM

	Month	Page
Heater-Core Removal (F)	Jan.	52
Don't Overlook Cooling System	Mar.	42
Pulley Installation on Water Pump (S)	Mar.	60
A New Look at Cooling System Problems	July	34
Cooling System Tip (F)	July	62
Substitute Replacement Hose (F)	July	64
Coolant Loss (S)	Nov.	60
Temperature Light Check (S)	Nov.	64
Cooling-System Service Tip (S)	Dec.	50

DRIVESHAFT AND UNIVERSAL JOINT

	Month	Page
Driveline Vibration Check (S)	Feb.	86
Driveshaft Removal (F)	May	60
Speed U-Joint Removal (F)	June	57
Keeps Prop Shaft Splines Clean (F)	June	60
Cures Driveline Thump (S)	Aug.	48

ELECTRICAL SYSTEM

	Month	Page
Uncover Hidden Headlight Faults Fast	Jan.	42
Turn-Signal Switch Removal (S)	Jan.	47
Easier Wiring Installation (F)	Jan.	52
Faster Generator Installation (F)	Jan.	52
Point Terminal Tool (F)	Jan.	54
Lamp Bulb Installation (S)	Feb.	86
False Ammeter Reading (S)	Feb.	88
Distributor Installation (F)	Feb.	90
Find Fuses, Circuit Breakers and Fusible Links Fast	Mar.	50
Spot Coil-Wiring Combinations (S)	Mar.	58
Headlight Aiming (S)	Mar.	58
Starter Removal (F)	Mar.	68
Roller Bearing Assembly F)	Mar.	68
Quick Solenoid Repair (F)	Mar.	68
Revised Distributor Sequence (S)	Apr.	48
Protects Instrument Cluster (S)	Apr.	50
New Ignition Resistance Specs (S)	Apr.	50
In-Line Fuse Locations (S)	Apr.	52
Spark-Plug Cable Connection (F)	Apr.	54
Starter-Cable Nut Tightener (F)	Apr.	54
Generator Alignment (F)	Apr.	56
Better Bulb Contact (F)	Apr.	56
Switch Replacement (S)	May	48
Hidden Distributor Problem (F)	May	58
Quick Alternator Check (F)	May	60
Holds Jumper Cable Grip (F)	June	57
Starting Tip (F)	June	60
Finds Signal-Light Trouble (F)	June	60
Spark-Plug Removal (S)	June	70
Thermostatic Vacuum-Switch Test (S)	June	72
Light-Switch Removal (S)	July	57
Turn-Signal Lamp Replacement (S)	July	57
Test Connections to Coil (F)	July	62
Accessory Fuse Check (S)	Aug.	46
Cluster Removal Caution (S)	Aug.	48
Meter Connection to Coil (F)	Aug.	65
Directional Lamp Ground (F)	Aug.	65
Rewinding Starter Drive (F)	Aug.	68
Checks Switch on Courtesy Light (F)	Aug.	68
Low Battery Check (S)	Sept.	64
Servicing 1968 Starter Armature (S)	Sept.	65
Corrects Faulty Start Switch (F)	Sept.	67
Changing Color of Corner Lamp (F)	Sept.	158
Secures Chevrolet Truck Alternator (F)	Oct.	36
Parking Lamp Ground (S)	Oct.	62
Truck Service: Taking on Regulators	Nov.	24
Intermittent Flashing of Side Lamp (S)	Nov.	60

THIS YEAR IN MOTOR

An index of the nearly 500 sales, management and service articles that have appeared in this magazine in 1968

SERVICE PROCEDURES

ACCESSORIES

	Month	Page
Servicing Plastic Wheels on Blowers (S)	Feb.	88
Mysterious Coolant Loss (S)	Mar.	58
Radiator Removal (S)	Mar.	58
Speedometer Removal (F)	Mar.	64
Faster Heater Core Removal (F)	Mar.	68
Quick Guide to Flasher Controls	Apr.	28
When Air Conditioners Lose Their Cool	Apr.	32
Heater Core Removal (S)	Apr.	50
Air-Conditioner Installation (S)	May	48
Instrument Cluster Removal (S)	May	52
Instrument Cluster Removal (S)	June	66
Heater Core Removal (S)	June	66
Windshield Wiper Check (S)	June	72
Moisture Removal from Cooler (S)	July	60
Thermostat Installation (F)	July	64
Heater or Cooler Control-Head Removal (S)	Aug.	46
Accessory Fuse Check (S)	Aug.	46
Evaporator Core Removal (S)	Aug.	46
Cluster Removal Caution (S)	Aug.	48
Vent-Hose Repair (F)	Sept.	67
Five Truck Wiper Faults You Can Repair	Oct.	30
Heater Motor Removal (F)	Oct.	38
Wiper-Blade Removal (S)	Oct.	64
Windshield-Wiper Replacement (S)	Oct.	64
Buick Power Top Repair (F)	Nov.	44
Drains Cooler Evaporation (F)	Nov.	96
Adds Oil to Cooler Compressor (F)	Dec.	42

AXLES

	Month	Page
New Specs for Axle End Play (S)	Feb.	86
Differential Repair (F)	July	62
Axle Bearing Replacement (F)	July	64
Tool to Remove Truck Axle Nut (F)	Aug.	68
New Thrust Spacers for Differential (S)	Oct.	60
Bent-Wheel Stud Removal (S)	Oct.	60

BRAKES

	Month	Page
Don't Be Stopped by the New Disc Brakes	Jan.	28
Master-Cylinder Disassembly (S)	Jan.	47
Brake Shudder Check (S)	Jan.	48
Bleeding Power Brakes (S)	Jan.	50
Bleeding Rear Disc Brakes (S)	Feb.	86
Easy Brake-Drum Removal (F)	Mar.	64
Overheating Rear Wheel Brakes (S)	Apr.	48
Bleeding Procedure Revised (S)	Apr.	50
Brake Job Speed-up (F)	Apr.	54
Power-Brake Bottoming (S)	May	56
Emergency Brake Adjustment (F)	May	64
Track Down Disc Brake Trouble Fast	June	32
Check Parking-Brake Adjustment	Aug.	52
Disc-Pad Installation (F)	Aug.	70
Correct Caliper Installation (S)	Sept.	65
Frees Stuck Emergency Cables (F)	Nov.	44
Corvair Brake Cable Installation (F)	Nov.	45
Brake Equalizer-Valve Adjustment (F)	Dec.	43

COOLING SYSTEM

	Month	Page
Heater-Core Removal (F)	Jan.	52
Don't Overlook Cooling System	Mar.	42
Pulley Installation on Water Pump (S)	Mar.	60
A New Look at Cooling System Problems	July	34
Cooling System Tip (F)	July	62
Substitute Replacement Hose (F)	July	64
Coolant Loss (S)	Nov.	60
Temperature Light Check (S)	Nov.	64
Cooling-System Service Tip (S)	Dec.	50

DRIVESHAFT AND UNIVERSAL JOINT

	Month	Page
Driveline Vibration Check (S)	Feb.	86
Driveshaft Removal (F)	May	60
Speed U-Joint Removal (F)	June	57
Keeps Prop Shaft Splines Clean (F)	June	60
Cures Driveline Thump (S)	Aug.	48

ELECTRICAL SYSTEM

	Month	Page
Uncover Hidden Headlight Faults Fast	Jan.	42
Turn-Signal Switch Removal (S)	Jan.	47
Easier Wiring Installation (F)	Jan.	52
Faster Generator Installation (F)	Jan.	52
Point Terminal Tool (F)	Jan.	54
Lamp Bulb Installation (S)	Feb.	86
False Ammeter Reading (S)	Feb.	88
Distributor Installation (F)	Feb.	90
Find Fuses, Circuit Breakers and Fusible Links Fast	Mar.	50
Spot Coil-Wiring Combinations (S)	Mar.	58
Headlight Aiming (S)	Mar.	58
Starter Removal (F)	Mar.	68
Roller Bearing Assembly F)	Mar.	68
Quick Solenoid Repair (F)	Mar.	68
Revised Distributor Sequence (S)	Apr.	48
Protects Instrument Cluster (S)	Apr.	50
New Ignition Resistance Specs (S)	Apr.	50
In-Line Fuse Locations (S)	Apr.	52
Spark-Plug Cable Connection (F)	Apr.	54
Starter-Cable Nut Tightener (F)	Apr.	54
Generator Alignment (F)	Apr.	56
Better Bulb Contact (F)	Apr.	56
Switch Replacement (S)	May	48
Hidden Distributor Problem (F)	May	58
Quick Alternator Check (F)	May	60
Holds Jumper Cable Grip (F)	June	57
Starting Tip (F)	June	60
Finds Signal-Light Trouble (F)	June	60
Spark-Plug Removal (S)	June	70
Thermostatic Vacuum-Switch Test (S)	June	72
Light-Switch Removal (S)	July	57
Turn-Signal Lamp Replacement (S)	July	57
Test Connections to Coil (F)	July	62
Accessory Fuse Check (S)	Aug.	46
Cluster Removal Caution (S)	Aug.	48
Meter Connection to Coil (F)	Aug.	65
Directional Lamp Ground (F)	Aug.	65
Rewinding Starter Drive (F)	Aug.	68
Checks Switch on Courtesy Light (F)	Aug.	68
Low Battery Check (S)	Sept.	64
Servicing 1968 Starter Armature (S)	Sept.	65
Corrects Faulty Start Switch (F)	Sept.	67
Changing Color of Corner Lamp (F)	Sept.	158
Secures Chevrolet Truck Alternator (F)	Oct.	36
Parking Lamp Ground (S)	Oct.	62
Truck Service: Taking on Regulators	Nov.	24
Intermittent Flashing of Side Lamp (S)	Nov.	60

	Month	Page
Stops Corrosion from Battery (F)	Dec.	43
Safety Relay for Power Windows (S)	Dec.	46
Ignition Point Failure (S)	Dec.	48

ENGINE

Connecting-Rod Position (S)	Jan.	47
Aids Cylinder-Head Removal (S)	Jan.	48
Simple Valve Seat Work (F)	Jan.	54
Retains Cylinders (F)	Feb.	95
Camshaft Removal (S)	Mar.	58
Color-Coded Bearings (S)	Mar.	60
Detecting Oil Leak (S)	Mar.	60
Tighter Manifold Cuts Oil Use (S)	Mar.	62
Broken Dipstick Tube Removal (F)	Mar.	64
Prevents Valve-Guide Damage (F)	Mar.	64
Hose Simplifies Piston Installation (F)	Mar.	68
Holds Gasket in Place (F)	Mar.	77
Fine Tune-Ups Demand Finest Instruments	Apr.	30
Head Tightening (S)	Apr.	48
Timing-Chain Installation (F)	Apr.	54
Diagnosing Lifter Noise (F)	Apr.	56
Expansion-Plug Installer (F)	Apr.	56
What's Different About "Closed" PCV Systems	May	30
Repair Stripped Head Bolt (F)	May	60
Crankcase Ventilator Cleaner (F)	May	64
New "Pressures" on the Vacuum System	June	34
Fast Valve Lap (F)	June	60
Removing Carbon from Manifold (F)	June	64
Easy Identification of '68 Engines	July	24
Teen-Age Tune-In	July	38
Crankcase Ventilator Filter (S)	July	57
Change in Push Rods and Tappets (S)	July	57
Installs Rear Main Seal Shim (F)	July	64
Easy Removal of Stuck Lifter (F)	Aug.	65
How to Tune-Up Imports Accurately	Sept.	58
Harmonic Balancer Removal on OH6 (S)	Sept.	64
Valve Adjustment Speeds Warm-Up (S)	Sept.	65
Removes Broken Dipstick Tube (F)	Sept.	66
Rocker-Shaft Replacement (F)	Sept.	158
Thermostat Removal Causes Overheating (S)	Oct.	62
Hydraulic Tappet Noise (S)	Oct.	62
New Piston Ring for Emission Control	Oct.	103
Temperature Light Check (S)	Nov.	64
Aids Removal of Stuck Lifter (F)	Nov.	96
Engine Rebuilding Tip (F)	Nov.	96
Adjusting Valves of Foreign Cars	Dec.	37
Don't Be Afraid of Truck Tune-Up	Dec.	40
Unclogs Oil Passage (F)	Dec.	42
Converter Interference (S)	Dec.	48

EXHAUST SYSTEM

Muffler Installation (F)	Mar.	68
Cures Power Loss (F)	Aug.	68
Tailpipe Stub Removal (F)	Sept.	67

EXHAUST EMISSION CONTROL

Smog Controls Demand New Timing	Jan.	32
Banishes Backfire (F)	Mar.	77
Desmoggers Change Carburetor Service	Apr.	36
What's Different About "Closed" PVC Systems	May	30
Quick Way to Service VW "Throttle Positioner"	Aug.	36
New Piston Ring for Emission Control	Oct.	103
What to Do About "Afterrunning"	Nov.	40
Hot Tips for Cold Starting	Dec.	30

FRONT END, STEERING

Power-Steering Pump Removal (S)	Jan.	48
Steering-Gear Lubrication (S)	Feb.	86
Steering-Wheel Removal (F)	Feb.	90
Now Align Front-End Faster	Mar.	54
Steering Wheel Installation (S)	Mar.	62
Wheel-Bearing Adjustment (S)	Apr.	48
Wheel-Bearing Lubrication (S)	May	52
Alignment Shim Adjustment (F)	May	60
Align Wheels Fast on '68 Imports	July	30
13 Tilt-Wheel Problems and How to Correct Them	Aug.	28
Installs Control-Arm Bushing (F)	Aug.	65
Power-Steering Adjustment (F)	Aug.	68
Power-Steering Pump Test (S)	Sept.	64
Front Shock-Absorber Removal (S)	Oct.	62
Shock-Absorber Removal (F)	Nov.	45
Proper Fluid Level in Power Steering (S)	Dec.	46
Quick Leveler Check (S)	Dec.	48

FUEL SYSTEM

Fuel Gauge Accuracy (S)	Jan.	48
Desmoggers Change Carburetor Service	Apr.	36
Fuel Injection Could Make a Comeback	Apr.	39
Corrects Stumble (S)	Apr.	50
Hard Cold Start (S)	May	52
Vacuum-Brake Adjustment (S)	June	66
Corrects Stumble and Stall (S)	June	66
Bent Choke Linkage (S)	July	57
Exhaust-Gas Analyzer Check (S)	July	58
Carburetor Air-Valve Bushing (S)	July	60
Allows Carburetor Adjustment (F)	July	66
Quick Way to Service VW "Throttle Positioner"	Aug.	36
Overhaul Cautions on Quadrajet (S)	Aug.	46
Lost Motion in Accelerator Linkage (S)	Aug.	48
Safeguard A.I.R. Housing (S)	Aug.	52
What's Different About Vacuum Diaphragm Choke Service	Sept.	62
Stop Stumble on Warm-Up (S)	Sept.	64
Stops Choke Valve Sticking (S)	Oct.	60
What to Do About "Afterrunning"	Nov.	40
Poor Acceleration Checks (S)	Nov.	60
Low Fuel-Gauge Reading (S)	Nov.	64
Hot Tips for Cold Starting	Dec.	30
Road Fix for Fuel Trouble (F)	Dec.	42

LUBRICATION

Grease Gun Regulator (F)	Jan.	54
Lubricating Overhaul Engine (F)	Apr.	56
Know All About the New Transmission Fluids	May	36
Oil-Filter Removal (S)	May	48
Primes Pump (F)	May	58
Reaching Inaccessible Filters (F)	June	57
Tidier Filter Removal (F)	June	60
Oil-Pressure Indicators (S)	July	58
Low Oil Pressure (S)	Dec.	46

ROAD SERVICE

Towing Tip (S)	Mar.	62
Road Service Tip (F)	Oct.	37
Jack and Lift Points for all '69 Cars	Nov.	34
Push and Tow Facts	Dec.	21

SUSPENSION

Rear Spring U-Bolt Replacement (S)	Jan.	46
Cleans U-Bolt Threads (F)	Feb.	90
Compresses Spring (F)	Mar.	68

TRANSMISSION, CLUTCH

When You Drain Automatic Drives	Jan.	34
Eliminating Hiss in Drive (S)	Jan.	47
Stops Clutch Chatter	Jan.	48
Magnet Cleans Automatic Drives (F)	Jan.	54
Clutch Squeak Cure (F)	Jan.	54
Drive Assembly Speeded (F)	Jan.	61
Corrects Upshift on Powerglide (S)	Feb.	86
Aids Truck Shift (F)	Feb.	90
Powerglide Disassembly Tip (F)	Feb.	95
Cold Starting Tip (S)	Mar.	60
Transmission Removal (S)	Apr.	48
Torqueflight Oil Filter (S)	Apr.	52
Snap-Ring Installation (S)	Apr.	52
Vacuum Modulator Tool (F)	Apr.	54
Test on Special Automatic (F)	Apr.	56
Shift Indicator Adjustment (F)	Apr.	61
Know All About the New Transmission Fluids	May	36
Tool Locates Transmission Center Support (S)	May	48
Turbo Hydra-Matic Oil Strainer (S)	May	48
Manual Transmission Noise (S)	May	56
Corrects Slip on 2-3 Shift (F)	May	58
Clutch-Spring Installation (F)	May	58
Roto Hydra-Matic Assembly (F)	May	60
How to Drain Converter (F)	June	57
Cleaning Powerglide Converter (F)	June	60
Four-Speed Linkage Adjustment (S)	June	66
Clutch Chatter in Reverse (S)	June	70
Transmission Drain Revised (S)	June	70
Transmission Rear-Seal Leak (S)	June	70
Clutch Noise (S)	July	58
Clutch Wear (S)	July	58
Replacement of Pump Bushing (F)	July	64
Eliminates Up-Shift Slip (F)	July	66
Fan Clutch Replacement (F)	Aug.	68

[CONTINUED ON PAGE 72

(S) = Service Slants
(F) = Fix It

	Month	Page
Keeping VW's New Automatic Stickshift Working	Oct.	28
Jetaway Clutch Installation (F)	Oct.	36
Camaro Transmission Removal (F)	Oct.	37
Corrects "No Drive" on Automatic (S)	Oct.	64
Clutch-Shaft End-Play Adjustment (S)	Nov.	60
Clutch-Plate Identification (S)	Nov.	64
Easy Clutch Installation (F)	Nov.	96
Transmission Removal Without Mess (F)	Dec.	43
Manual Shift-Lever Adjustment (F)	Dec.	43
Shift Cable Bind (S)	Dec.	48

WHEELS, TIRES

Stuck Tire Solution (F)	Jan.	52
Tire Rotation Essential (S)	Mar.	60
Adapts Wheel to Tire Change (F)	July	64
Tire Trends: New, Safer Tire Repair Methods	Aug.	22
Disc-Brake Wheel Balance (F)	Oct.	37
Truck Service: Taking on Tires	Nov.	26

BODY AND FRAME

Proper Alignment Speeds Body Repair	Jan.	38
Tailgate Locks (S)	Jan.	50
Front Fender Alignment (S)	Jan.	50
Plastic Molding Retainers (S)	Jan.	50
Correcting Minor Paint Damage (S)	Jan.	50
Rear-Bumper Removal (F)	Jan.	61
Hose Saves Windshield (F)	Jan.	61
Old Glass Sealer Remover (F)	Jan.	61
Aligns Door Glass (S)	Feb.	88
Notch Checks Glass Height (S)	Feb.	88
Primer Surfacer for Paint Repair (F)	Feb.	95
Bumper-End Replacement (F)	Feb.	95
Inside Handle Installation (F)	Feb.	95
New Adhesive Simplifies Decal Application	Mar.	44
Cleaning Seat Fabric (S)	Mar.	62
Nylon Molding Retainers (S)	Mar.	62
Door Glass Replacement (S)	Mar.	62
Halts Window Rattle (S)	Mar.	62
Quick Bumper Removal (F)	Mar.	77
Holds Door Open (F)	Mar.	77
Adjust Trunk Lids Right the First Try	Apr.	42
Corner-Cap Installation (S)	Apr.	52
Stencils for Striping (S)	Apr.	52
Tape Sticks to Weatherstrip (F)	Apr.	61
Fiberglass Scratch Prevention (F)	Apr.	61
Sheet-Metal Straightener (F)	Apr.	61
Careful Cuts Speed Camaro Quarter Repair	May	28
Door-Pull Handle Removal (S)	May	56
Stops Wind Whistle (S)	May	56
Prevents "Fish-Eye" Trouble (F)	May	64
Spray Spares Cleaner (F)	May	64
Drilling Newly Painted Panels (F)	May	64
Repairing Quarter Panel (F)	May	64
Unbending a Volvo American Style	June	36
Solves Door Glass Problem (F)	June	64
Shrinking Panel Hi-Spots (F)	June	64
Easy Molding Installation (F)	June	64
Bumper Clearance at Hood (S)	June	72
Adjusts Torsion Bar on Deck Lid (S)	June	72
Balance Weight on Wheel Cover (S)	June	72
Front Bumper Removal (S)	July	60
Headlamp-Door Cover Alignment (S)	July	60
Eliminates Hood Rattle (S)	July	60
Headlight Spring Installation (F)	July	62
Tightens Armrest (F)	July	66
Masking Paint on Chrome (F)	July	66
Tailgate Hinge Repair (F)	July	66
Wagon Repair More Than "Skin" Deep	Aug.	30
Auxiliary-Seat Adjustment on 75s (S)	Aug.	52
Top-Boot Installation (S)	Aug.	52
Repair for Stripped Armrest Screw (S)	Aug.	52
Adjustable Sandpaper Backer (F)	Aug.	70
Vinyl Top Repair (F)	Aug.	70
Glass-Channel Repair (F)	Aug.	70
Getting a Line on Front-End Replacement	Sept.	60
Smooths Steering Wheel Scratches (S)	Sept.	65
Split-Level Body Shop	Oct.	33
Door-Handle Replacement (F)	Oct.	38
Shaping Tight Contours (F)	Oct.	38
Knob Adjustment of Locking Rod (S)	Oct.	64
Locates Rattle (S)	Oct.	64
Solution Simplifies Decal Application	Nov.	30
Repair of Vertical Grille (S)	Nov.	66
Cleaning Smoke Stains (S)	Nov.	66
Installing Side Moldings (S)	Nov.	66
Welding Tip (F)	Nov.	102
Sizing Speed Fasteners (F)	Nov.	102
Accurate Measuring Means Proper Fit	Dec.	28
Freeing Frozen Door Lock (S)	Dec.	50
Corrects Door Hinge Binding (S)	Dec.	50
Aids Glove-Box Door Opening (S)	Dec.	50
Gives Door "Solid" Sound (F)	Dec.	52
Body Rattle in Chevelle (F)	Dec.	52
Cleans Spray Gun (F)	Dec.	52

NEW CAR SERVICE

Service on the '68s	Feb.	50
Cooling System	Feb.	51
Brakes	Feb.	52
Tune-Up	Feb.	54
Front End, Steering, Suspension	Feb.	56
Safety Accessories	Feb.	58
Exhaust System	Feb.	59
Starter, Charging System Lights	Feb.	60
Body, Frame	Feb.	62
Engine	Feb.	64
Comfort Accessories	Feb.	66
Transmission	Feb.	67
Hood Latch, Gas Filler Neck Locations on '69 Cars	Oct.	24

LAYOUTS, TOOLS EQUIPMENT

Aid in Tap Alignment (F)	Jan.	52
Air-Line Antifreeze (F)	Jan.	54
Cleans U-Bolt Threads (F)	Feb.	90
Hub Caps Reflects Lights (F)	June	60
Tool to Remove Truck Axle Nut (F)	Aug.	68

SERVICE MANAGEMENT

Consumer Demand to Expand in 1968	Jan.	22
Safety Can Be Sold	Feb.	68
New Safety Standard Affects Replacement Parts	Mar.	32
Equal Employment Law Touches More Shops	Apr.	38
Let an Electronic Brain Keep Your Books	Apr.	44
Sometimes You Have to Hold Her Hand	May	10
Does PMVI Actually Reduce Accidents?	May	24
Mechanic Shortage		
Looking at the Problem	June	21
What They Are Saying . . . Doing . . . Planning	June	22
Using Tools and Equipment to Boost Volume	June	24
Keeping Your Mechanics	June	27
Training Your Mechanics	June	28
Where They're Training	June	29
Job Corp . . . Enlisting Mechanics for Tomorrow	June	30
She's Got Her Eye on You	June	48
First Look at Controversial Body Shop	July	21
Take the Risk Out of Operating Your Shop	July	28
Detroit's No. 1 Maverick Speaks for Himself	Aug.	25
Opens Clinic for Split Second Troubleshooting	Aug.	34
What She Really Wants to Know	Aug.	40
Add a Woman to Your Staff	Oct.	12
Can Detroit Stem the Import Tide?	Oct.	21
Drag Racing Today	Oct.	26
Split-Level Body Shop	Oct.	33
Lift for Profits	Oct.	40
Truck Service: Can You Handle It?	Nov.	21
Truck Service: Keep Your Inventory Moving	Nov.	28
Mechanic Shortage No Stranger to British Service	Nov.	37
Keep Your Shop Going After a Fire	Dec.	32

SERVICE SALES

Service Market Outlook Brightest Ever	Jan.	24
Whole After-Market Looks for Gains	Jan.	26
Develop Your Own Success Formula	Jan.	37
Like More Customers? Here's How to Get Them	Feb.	38
There's Profit in Promoting Performance	Feb.	40
They'll Pay for New Car Appearance	Feb.	42
They're Ready to Buy Safety	Feb.	44
It's Easy to Sell Comfort	Feb.	46
Sell the Idea of Saving Money	Feb.	48
Your Customers Want Reliability and Speed	Mar.	16

(S) = Service Slants
(F) = Fix It

	Month	Page
Cash In on Credit Without Risk	Mar.	46
Put a "Hitch" in Their Vacations	Mar.	53
Forget Competitors, Just Sell	Apr.	8
Check Lanes Lead to More Business	Apr.	35
Car Air Conditioning a Hot Market	May	26
Don't Try to Outtalk Customers	May	44
Antique Cars for Fun and Profit	June	38
Let Enthusiasm Make the Sale	June	52
Three Magic Words to Help You Sell	July	46
Concentrate on Cooling Systems	July	52
Three Giant Steps to More Service Volume	Aug.	32
Sell Like a General	Aug.	57
Promotions for Profit	Sept.	73
8 Ways to Drum Up Business	Sept.	74
Let the Mailman Sell for You	Sept.	74
How to Set Up a Direct Mail Program	Sept.	77
Newspaper Ads Are a Good Buy for Shops	Sept.	78
Let Radio Turn Your Customers On	Sept.	79
Win Customers with Premiums	Sept.	80
Signs and Displays Point the Way to More Sales	Sept.	82
Let Your Telephone Ring Up More Sales	Sept.	84
Let the Billboard Tell Your Story	Sept.	85
Put Personal Touch in Your Selling	Sept.	87
Feel Well to Sell Well	Oct.	56
Nine Car Services to Sell Truck Owners	Nov.	26
Mini Clinic Builds Maxi Sales	Nov.	43
How Warranty Changes Help You	Dec.	25

TBA, MERCHANDISING

	Month	Page
Puts Art in TBA Selling	Jan.	30
Cleans Up on Wiper Replacement	Feb.	18
Proper Pitch Turns Belt Sales On	Apr.	46
Secrets of a Shock Absorber Specialist	May	14
"How I Made Wiper Blades My Biggest Seller"	June	12
How All-Out Drives Sell 100 Tires a Month	July	26
Commissions Sell 65 Belts a Week	Aug.	41
Inspection Heats Up Thermostat Sales	Oct.	39
Formula for Selling 50 Batteries a Month	Nov.	42
He Sells 120 Tires a Month	Dec.	36

TECHNICAL, DESIGN DEVELOPMENTS

	Month	Page
Can Surgery Save the Internal Combustion Engine?	Mar.	40
Gas Bags to Lessen Crash Impact?	Mar.	48
Automobile to Lose Star Billing?	Apr.	26
Fuel Injection Could Make a Comeback	Apr.	39
Whines and Turbines at Indy	May	22
Chipless Paint on the Way?	May	38
Detroit Testing Plastic Parts	June	40
What's Around the Bend for Tomorrow's Automobile	July	32
Foam-Filled Tires Next?	July	36
Tire Trends	Aug.	21
What's Ahead in Safety Standards?	Aug.	24
Computers: Leave the Driving to Us	Aug.	38
Steam Car Controversy Boils Over	Sept.	150
Detroit Looks at Speed-Limiting Devices	Oct.	69
Can the Steam Car Make It?	Nov.	32
Can Detroit Build a Perfect Car?	Dec.	33

CAR REGISTRATIONS

	Month	Page
2 Million More Cars Crowd Road	July	44
US Motor Vehicle Population Just Short of 100 Million	Oct.	41

NEW CAR DESCRIPTIONS

	Month	Page
American Motors '69	Sept.	56
American Motors AMX	Feb.	76
Aston-Martin DBS Four-Seater	Jan.	93
Austin America	May	132
Buick '69	Sept.	49
Cadillac '69	Sept.	55
Checker Marathon	May	96
Checker Marathon Diesel	Nov.	90
Chevrolet '69	Sept.	50
Chrysler '69	Sept.	43
Chrysler Newport	Apr.	98
Diamond Reo	May	98
Diamond Reo CF-59	Mar.	136
Dodge '69	Sept.	40
Dodge Trucks	Sept.	166
Exemplar I	Feb.	126
Ford '69	Sept.	44
Ford Cortina Deluxe	Feb.	172
Ford Econoline	Mar.	112
Ford Economy Mustang	Dec.	88
Ford Techna	Aug.	90
Ford Trucks	Sept.	166
GMC Trucks	Nov.	120
Imperial '69	Sept.	42
International Accent Flavors Midyear Entries	May	33
International Harvester Transtar	Sept.	147
International Unveils Turbine Tractor Prototype	Feb.	96
Jaguar XJ	Oct.	96
Jaguar XK-B Two-Seater	Jan.	102
Lincoln '69	Sept.	48
Lincoln Continental Mark III	Mar.	146
Mercedes Benz 280 SE	May	118
Mercury '69	Sept.	47
Mercury Cougar XR7-G	Mar.	130
Mercury Parklane	Feb.	158
Nissan Datsun Pick-Up	Jan.	112
Oldsmobile '69	Sept.	53
Opel Kadett '69	Dec.	92
Plymouth '69	Sept.	38
Plymouth Road Runner Hardtop	Mar.	116
Pontiac '69	Sept.	52
Pontiac Bonneville	Apr.	121
Simca 1000	Mar.	137
Subaru 360	June	110
Volkswagen '69	Oct.	84